


ST-C112(C)

1/2" AIR REVERSIBLE DRILL (WITH KEYLESS CHUCK)



PARTS LIST

No.	Parts No.	Description	Q'ty
1	C112-01	Inlet Bushing	1
2	C112-02	Deflector	1
3	C112-03	Valve Spring	1
4	C112-04	Valve	1
5	C112-05	Valve Seat	1
6	C112-06	Spacer	1
7	C112-07	Silencer	1
8	C112-08	Composite Housing	1
9	C112-09	Reverse Valve Lever	1
10	C112-10	Taping Screw (Φ2.3x12L)	1
11	C112-11	O-Ring (3x1)	1
12	C112-12	Trigger	1
13	C112-13	O-Ring (27x2)	2
14	C112-14	Valve Body	1
15	C112-15	Bearing (626)	2
16	C112-16	Rear Plate	1
17	C112-17	Spring Pin (Φ2.5x5.0L)	3
18	C112-18	Rotor	1
19	C112-19	Rotor Blade	5
20	C112-20	Cylinder	1
21A	C112-21A	Front Plate	1

No.	Parts No.	Description	Q'ty
23A	C112-23A	Pin (Φ2.5x5.8L)	1
24A	C112-24A	Internal Gear	1
24B	C112-24B	Internal Gear	1
25	C112-25	Pinion Gear	1
26	C112-26	Idler Gear	6
27	C112-27	Pin (Φ4x13.8)	1
28	C112-28	Reduction Spindle	1
29	C112-29	Reduction Gear	1
30	C112-30	Work Spindle	1
31	C112-31	Ball Bearing (6201ZZ)	2
32A	C112-32A	Gear Housing	1
33	C112-33	Chuck Spacer	1
34	C112-34	Drill Chuck [ST-C112]	1
	C112-34C	Keyless Chuck [ST-C112C]	1
35A	C112-35A	Screw (M5x25L)	1
36	C112-36	Key (1/2")	1
37	C112-37	Clamp Ring	1
38	C112-38	Rubber Gasket	1
39	C112-39	Hand Handle	1
40	C112-40	Screw	1